

Dimmer Products

My 5942 will turn on via the Micro USB but will not power up via the Power + & - port.

You have likely blown a fuse and the 5942 will need to come in to be serviced on an RMA. This type of failure voids the any warranty the product has and the customer will have to pay for this repair.

Unique solution ID: #1008

Author: Jannelle Boisseau

Last update: 2022-10-25 18:28