

# Multiverse Transmitter

## I can't factory default my 5910/5911/5912.

This is a known bug in the 2.0.0.0.9.4 software. We are working to resolve this. There is no known work around at this time.

Unique solution ID: #1170

Author: Jannelle VanEtten

Last update: 2023-09-27 14:28